

H.C.B-B1421 BMW (2.0 N47/ 3.0 N57) DIESEL ENGINES CRANKSHAFT LOCKING TOOL



- * Without it, it's IMPOSSIBLE to replace: The oil pump chain, both timing chains, the gear of the high pressure pump and of the balancer shaft.
- * The N47 engine family is prone to excessive timing chain wear and premature failure. Rattling noise

Rating: Not Rated Yet

Price:

Sales price:

Discount:

[Ask a question about this product](#)

Manufacturer: [HCB Specialty Tools](#)

Description

STEP 1

STEP 2

STEP 3

STEP 4

STEP 5

STEP 6

STEP 7

STEP 8
